



1/5

Figure 1



2/5

Figure 2





SUBSTITUTE SHEET (RULE 26)



3/5

Figure 3a**Figure 3b**

4 / 5

Figure 3cFigure 3d

5/5

Figure 4Figure 5

Motor:
L=6 connection;
3rd harmonic drive;
72-degree phase angle

Resistor array:
L=5 connection;
3rd harmonic drive;
0-degree phase angle